

VCDS

Windows Based VAG/VAS Emulator Running on Windows 10 x64

Version: Release 21.3.0

www.Ross-Tech.com

Dealer/Shop Name: ZUM Samar

Workshop Code: 999 00418

Diagnostic Trouble Code Report

Friday,26,August,2022,20:26:38:00009

VIN: TMBJJ7NP7J7532421 License Plate: SKODA CIN

Mileage: Repair Order:

Control Module Part Number: 5Q0 907 686 C HW: 5Q0 907 686 C

Component and/or Version: HRE\_Master H12 0080

Software Coding: 02032103

Work Shop Code: WSC 00418 999 12345

ASAM Dataset: EV\_HREntryHella 001028 (SK48)

VCID: 3D718CF3AC71A763E8-8068

3 Faults Found:

337168 - Databus

U1121 00 [009] - Missing Message

[New feature! Extended UDS fault detail is only supported by current gen. interfaces]

Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 6

Fault Frequency: 1

Reset counter: 23

Mileage: 82970 km

Date: 2022.08.26

Time: 20:21:04

337216 - Databus

U1121 00 [009] - Missing Message

[New feature! Extended UDS fault detail is only supported by current gen. interfaces]

Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 6

Fault Frequency: 1

Reset counter: 23

Mileage: 82970 km

Date: 2022.08.26

Time: 20:21:04

VCDS  
Diagnostic Trouble Code Report  
Control Module Part Number: 5Q0 907 686 C  
Page 2

337296 - Databus

U1121 00 [009] - Missing Message

[New feature! Extended UDS fault detail is only supported by current gen. interfaces]

Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 6

Fault Frequency: 1

Reset counter: 23

Mileage: 82970 km

Date: 2022.08.26

Time: 20:21:04